

## STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

PAT MCCRORY GOVERNOR ANTHONY J. TATA SECRETARY

March 19, 2015

MEMORANDUM TO:

Joey Hopkins, P.E.

Division 5 Engineer

ATTENTION:

Lisa B. Gilchrist, E.I.

Division Bridge Program Manager

FROM:

Kyung (K. J.) Kim, Ph.D., P.E.

Eastern Regional Geotechnical Manager

STATE PROJECT:

41665.3E (SF-720014)

FEDERAL PROJECT:

N/A

COUNTY:

Person

DESCRIPTION:

Bridge No. 14 on NC 157 over Byrd's Creek between SR 1115

and SR 1119

SUBJECT:

**Bridge Foundation Recommendations** 

The Geotechnical Engineering Unit has completed the subsurface investigation and has prepared the foundation design recommendations for the above structure and presents the following project data:

X Bridge Inventory (10) pages
X Foundation Design Recommendations (3) pages
Design Calculations ( ) pages
Special Provisions ( ) pages

Please call Nadia Al-Dhalimy, P.E. or Chris Kreider, P.E. at (919) 662-4710 if there are any questions concerning this memorandum.

KJK/CAK/NAA

MAILING ADDRESS: EASTERN REGIONAL OFFICE GEOTECHNICAL ENGINEERING UNIT 1570 MAIL SERVICE CENTER RALEIGH NC 27699-1570 TELEPHONE: 919-662-4710 FAX: 919-662-3095

WEBSITE: WWW.DOH.DOT.STATE.NC.US

LOCATION:

3301 JONES SAUSAGE RD., SUITE 100 GARNER, NC 27529-9489

## **FOUNDATION RECOMMENDATIONS**


PROJECT 41665.3E DESCRIPTION Bridge No. 14 on NC 157

T.I.P. NO. SF-720014 over Byrd's Creek between SR 1115 and SR 1119

COUNTY Person

STA0TION 16+91.50 -L-

DESIGN NAA 3/19/2015
CHECK M 3/19/16
APPROVAL M 3/19/16



BENT NO.	STATION	FOUNDATION TYPE	FACTORED RESISTANCE	MISCELLANEOUS DETAILS
END BENT	16+52.88 -L-	Cap on HP 12 x 53 Steel Piles	100 Tons/Pile	Bottom of Cap Elevation = 553.7 ft. ± Estimated Pile Length = 10 ft. ± Number of Vertical Piles = 5 Number of Braced Piles = 2
END BENT 2	17+30.13 -L-	Cap on HP 12 x 53 Steel Piles	100 Tons/Pile	Bottom of Cap Elevation = 554.5 ft. ± Estimated Pile Length = 10 ft. ± Number of Vertical Piles = 5 Number of Braced Piles = 2

**COMMENTS & NOTES** (See Following Page)

#### **FOUNDATION RECOMMENDATION NOTES ON PLANS**

- 1. FOR PILES, SEE SECTION 450 OF THE STANDARD SPECIFICATIONS.
- 2. PILES AT END BENT NO. 1 AND END BENT NO. 2 ARE DESIGNED FOR A FACTORED RESISTANCE OF 100 TONS PER PILE.
- 3. PILE EXCAVATION IS REQUIRED TO INSTALL PILES AT END BENT NO. 1 AND END BENT NO. 2. EXCAVATE HOLES AT PILE LOCATIONS TO ELEVATIONS 543.7 FT AND 544.5 FT, RESPECTIVELY. FOR PILE EXCAVATION, SEE SECTION 450 OF THE STANDARD SPECIFICATIONS.
- 4. CONCRETE OR GROUT IS REQUIRED TO FILL HOLES FOR PILE EXCAVATION AT END BENT NO. 1 AND END BENT NO. 2.

#### **SPECIAL NOTE ON PLANS**

5. DO NOT DRIVE PILES AT END BENT NO. 1 AND END BENT NO. 2 AFTER PLACING PILES IN HOLES. VERIFY PILES ARE SEATED ON HARD ROCK BEFORE FILLING WITH CONCRETE OR GROUT.

#### FOUNDATION RECOMMENDATION COMMENTS

- 1. 1.5:1 (H:V) END SLOPE WITH SLOPE PROTECTION IS OK FOR BOTH END BENTS.
- 2. REINFORCED BRIDGE APPROACH FILL DETAIL SHOULD BE USED AT BOTH END BENTS. SEE STANDARD DRAWING NO. 422.10 "REINFORCED BRIDGE APPROACH FILLS" PER NCDOT 2012 ROADWAY STANDARD DRAWINGS.
- 3. NO WAITING PERIOD IS REQUIRED BEFORE BEGINNING ANY WORK FOR END BENT CONSTRUCTION AFTER COMPLETION OF THE EMBANKMENT AT EACH END BENT.

Designed by: NAA Date: 3/19/2015 Checked by: 1/4 Date: 3/19/15

### PILE PAY ITEMS

(Revised 8/15/12)

WBS ELEMENT_	41665.3E	DATE 3/19/2015
TIP NO.	SF-720014	DESIGNED BY NAA
COUNTY	Person	CHECKED BY CAK
STATION	16+91.50 -L-	_
DESCRIPTION_	Bridge No. 14 on NC 157 over Byro	d's Creek between SR 1115 and 1119
NUMI NUMBER OF	R OF BENTS WITH PILES BER OF PILES PER BENT END BENTS WITH PILES OF PILES PER END BENT 7	Only required for "Predrilling for Piles" & "Pile Excavation" pay items

		PI	LE PAY ITEN	I QUANTIT	TIES				
		Pile							
	Steel				Exca	avation			
	Pile	Pipe Pile	Predrilling	Pile	(per l	inear ft)	PDA		
Bent # or	Points	Plates	For Piles	Redrives	In	Not In	Testing		
End Bent #	(yes/no)	(yes/no/maybe)	(per linear ft)	(per each)	Soil	Soil	(per each)		
End Bent #1					35	35			
End Bent #2					34	36	\ /		
							\		
							\ /		
							V		
							$\land$		
							/ \		
							/ \		
							/ \		
TOTALS	$>\!\!<$		0	0	69	71	0		

#### Notes:

Blanks or "no" represent quantity of zero.

If steel pile points are required, calculate quantity of "Steel Pile Points" as equal to the number of steel piles.

If pipe pile plates are or may be required, calculate the quantity of "Pipe Pile Plates" as equal to the number of pipe piles.

Show quantity of "PDA Testing" on the plans as total only.

If quantity of "PDA Testing" is 3 or less, reference "Pile Driving Criteria" provision in PDA notes on plans and include "Pile Driving Criteria" provision in the contract.

SF-720014	CONTENTS  SHEET NO.  1 2 3 4 5 6-8 9 10	DESCRIPTION TITLE SHEET LEGEND SITE PLAN PROFILE CROSS SECTIONS BORE LOGS CORE PHOTOGRAPH SITE PHOTOGRAPH	S
REFERENCE: SF-720014			
41665			
ROJECT: 41665			

## STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DIVISION OF HIGHWAYS GEOTECHNICAL ENGINEERING UNIT

## **STRUCTURE** UBSURFACE INVESTIGATION

COUNTY PROJECT	PERSON DESCRIPTION	BRIDGE	NO. 14	ON	NC	157
(GUES	S RD.) OVER	BYRD'S	CREEK			
SITE DE	SCRIPTION	1.3				

STATE STATE PROJECT REFERENCE NO. NO SHEETS SF-720014

#### CAUTION NOTICE

THE SUBSURFACE INFORMATION AND THE SUBSURFACE INVESTIGATION ON WHICH IT IS BASED WERE MADE FOR THE PURPOSE OF PREPARING THE SCOPE OF WORK TO BE INCLUDED IN THE REQUEST FOR PROPOSAL. THE VARIOUS FIELD BORING LOGS, ROCK CORES AND SOIL TEST DATA AVAILABLE MAY BE REVIEWED OR INSPECTED IN RALEIGH BY CONTACTING THE N. C. DEPARTMENT OF TRANSPORTATION, GEOTECHNICAL ENGINEERING UNIT AT 1919) TOT-6850, THE SUBSURFACE PLANS AND REPORTS, FIELD BORING LOGS, ROCK CORES AND SOIL TEST DATA ARE NOT PART OF THE CONTRACT.

SOIL AND ROCK BOUNDARIES WITHIN A BOREHOLE ARE BASED ON GEOTECHNICAL INTERPRETATION UNLESS ENCOUNTERED IN A SAMPLE, INTERPRETED BOUNDARIES MAY NOT NECESSARLY REFLECT ACTUAL SUBSUIFFACE CONDITIONS BETWEEN SAMPLED STRATA AND BOREHOLE INFORMATION MAY NOT NECESSARLY REFLECT ACTUAL SUBSUIFFACE CONDITIONS BETWEEN BORINOS, THE LABORATORY SAMPLE DATA AND THE IN SITU (IN-PLACE) TEST DATA CAN BE RELIED ON ONLY TO THE DEGREE OF RELIABILITY INHERITY IN THE STANDARD TEST METHOD. THE OBSERVED WATER LEVELS OR SOIL MOISTURE CONDITIONS INDICATED IN THE SUBSUIFFACE INVESTIGATIONS ARE AS RECORDED AT THE TIME OF THE INVESTIGATION. THESE WATER LEVELS OR SOIL MOISTURE CONDITIONS HAY VARY CONSIDERABLY WITH TIME ACCORDING TO CLIMATIC CONDITIONS INCLUDING TEMPERATURES, PREFIRED TAIL AND WIND AS WELL AS OTHER NON-LIMATIC FACTORS. PRECIPITATION AND WIND, AS WELL AS OTHER NON-CLIMATIC FACTORS.

THE BIDDER OR CONTRACTOR IS CAUTIONED THAT DETAILS SHOWN ON THE SUBSURFACE PLANS ARE PRELIMINARY ONLY AND IN MANY CASES THE FINAL DESIGN DETAILS ARE DIFFERENT FOR BIDDING AND CONSTRUCTION PURPOSES, REFER TO THE CONSTRUCTION PLANS AND DOCUMENTS FOR FINAL DESIGN INFORMATION ON THIS PROJECT. THE DEPARTMENT DOES NOT MARRANT OR GUARANTEE THE SUFFICIENCY OR ACCURACY OF THE INVESTIGATION MADE, NOR THE INTERPRETATIONS MADE, OR OPINION OF THE DEPARTMENT AS TO THE TYPE OF MATERIALS AND CONDITIONS TO BE ENCOUNTERED. THE BIDDER OR CONTRACTOR IS CAUTIONED TO MAKE SUCH INDEPENDENT SUBSURFACE INVESTIGATIONS AS HE DEEMS NECESSARY TO SATISTY HIMSELF AS TO CONDITIONS TO BE ENCOUNTERED ON THE PROJECT. THE CONTRACTOR SHALL HAVE NO CLAIM FOR ADDITIONAL COMPENSATION OR FOR AN EXTENSION OF TIME FOR ANY REASON RESULTING FROM THE SOTULAL CONDITIONS ENCOUNTERED AT THE SITE DIFFERING FROM THOSE INDICATED IN THE SUBSURFACE INFORMATION.

NOTES:

1. THE INFORMATION CONTAINED HEREIN IS NOT IMPLIED OR GUARANTEED BY THE N.C. DEPARTMENT OF TRANSPORTATION AS ACCURATE NOR IS IT CONSIDERED PART OF THE PLANS, SPECIFICATIONS OR CONTRACT FOR THE PROJECT.

2. BY HAVING REQUESTED THIS INFORMATION, THE CONTRACTOR SPECIFICALLY WAIVES ANY CLAIMS FOR INCREASED COMPENSATION OR EXTENSION OF TIME BASED ON DIFFERENCES BETWEEN THE CONDITIONS INDICATED HEREIN AND THE ACTUAL CONDITIONS AT THE PROJECT SITE.

D.G. PINTER C.E. CONGLETON INVESTIGATED BY N.D. MOHS DRAWN BY N.D. MOHS


PERSONNEL

N.D. MOHS J.R. SWARTLEY

CHECKED BY N.T. ROBERSON

SUBMITTED BY N.T. ROBERSON

DATE MARCH 2015



SF-720014

2


SF-72


# NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS GEOTECHNICAL ENGINEERING UNIT


## SUBSURFACE INVESTIGATION

SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS

SOIL DESCRIPTION	GRADATION	ROCK DESCRIPTION	TERMS AND DEFINITIONS
SOIL IS CONSIDERED UNCONSOLIDATED, SEMI-CONSOLIDATED, OR WEATHERED EARTH MATERIALS THAT CAN BE PENETRATED WITH A CONTINUOUS FLIGHT POWER AUGER AND YIELD LESS THAN 100 BLOWS PER FOOT ACCORDING TO THE STANDARD PENETRATION TEST (AASHTO T 206, ASTM DI508, SOIL CLASSIFICATION IS BASED ON THE AGSHTO SYSTEM, BASIC DESCRIPTIONS GENERALLY INCLUDE THE FOLLOWING; CONSISTENCY, COLOR, TEXTURE, MOISTURE, AASHTO ELASSIFICATION, AND OTHER PERTINENT FACTORS SUCH AS MINERALOGICAL COMPOSITION, ANSULARITY, STRUCTURE, PLASTICITY, ETC. FOR EXAMPLE,	WELL GRADED - INDICATES A GOOD REPRESENTATION OF PARTICLE SIZES FROM FINE TO COARSE.  UNIFORMLY GRADED - INDICATES THAT SOIL PARTICLES ARE ALL APPROXIMATELY THE SAME SIZE.  GAP-GRADED - INDICATES A MIXTURE OF UNIFORM PARTICLE SIZES OF TWO OR MORE SIZES.  ANGULARITY OF GRAINS  THE ANGULARITY OR ROUNDNESS OF SOIL GRAINS IS DESIGNATED BY THE TERMS.	HARD ROCK IS NON-COASTAL PLAIN MATERIAL. THAT VOULD YIELD SPT REFUSAL IF TESTED, AN INFERRED ROCK LINE INDICATES THE LEVEL AT WHICH NON-COASTAL PLAIN MATERIAL WOULD YIELD SPT REFUSAL. SPT REFUSAL IS PENETRATION BY A SPLIT SPOON SAMPLER COUAL TO OR LESS THAN 0.1 FOOT PER 60 BLOWS IN NON-COASTAL PLAIN MATERIAL. THE TRANSITION BETWEEN SOIL AND ROCK IS OFTEN REPRESENTED BY A ZONE OF WEATHERED ROCK.  ROCK MATERIALS ARE TYPICALLY DIVIDED AS FOLLOWS:	ALLUVIUM (ALLUV.) - SOILS THAT HAVE BEEN TRANSPORTED BY WATER,  ADUJEER - A WATER BEARING FORMATION OR STRATA.  ARENACEOUS - APPLIED TO ROCKS THAT HAVE BEEN DERIVED FROM SAND OR THAT CONTAIN SAND,  AROLLACEOUS - APPLIED TO ALL ROCKS OR SUBSTANCES COMPOSED OF CLAY MINERALS, OR HAVING
VERY STIFF,GRAY,SILTY CLAY,MOIST WITH INTERBEDDED FINE SAND LAVERS,HIGHLY PLASTIC,A-7-6	ANGULAR, SUBANGULAR, SUBROUNDED, OR ROUNDED.  MINERAL DOICAL COMPOSITION  MINERAL NAMES SUCH AS DUARTZ, FELDSPAR, MICA, TALC, KAOLIN, ETC.  ARE USED IN DESCRIPTIONS WHEN THEY ARE CONSIDERED OF SIGNIFICANCE.	WEATHERED ROCK (WR)  NON-COASTAL PLAIN MATERIAL THAT WOULD YIELD SPT N VALUES > 100 BLOWS PER FOOT IF TESTED.  CRYSTALLINE ROCK (CR)  FINE TO COARSE GRAIN IGNEOUS AND METAMORPHIC ROCK THAT WOULD YIELD SPT REFUSAL IF TESTED. ROCK TYPE INCLUDES GRANITE, CNEISS, GABBRO, SCHIST, ETC.	A NOTABLE PROPORTION OF CLAY IN THEIR COMPOSITION, SUCH AS SHALE, SLATE, ETC.  ARTESIAN - GROUND WATER THAT IS UNDER SUFFICIENT PRESSURE TO RISE ABOVE THE LEVEL AT WHICH IT IS ENCOUNTERED, BUT WHICH DOES NOT NECESSARILY RISE TO OR ABOVE THE GROUND SUFFACE.  CALCAREOUS (CALC.) - SOILS THAT CONTAIN APPRECIABLE AMOUNTS OF CALCIUM CARBONATE.
CLASS. A-1-b A-1-b A-2-4 A-2-5 A-2-6 A-2-7 R2-5 A-2-7 SYMBOL COORDINATE A-2-1 A-2-5 A-2-6 A-2-7 R2-3 A-5 A-7 R2-3 A-5 A-7 R2-3 R2-3 R2-3 R2-3 R2-3 R2-3 R2-3 R2-3	COMPRESSIBILITY  SLIGHTLY COMPRESSIBLE LL < 31 MODERATELY COMPRESSIBLE LL = 31 - 50 HIGHLY COMPRESSIBLE LL > 50  PERCENTAGE OF MATERIAL	NON-CRYSTALLINE ROCK (NCR) SEDIMENTARY ROCK THAT WOULD YELLO SPT REFUSAL PLAIN SEDIMENTARY ROCK THAT WOULD YELLO SPT REFUSAL IF TESTED. ROCK TYPE INCLUDES PHYLLITE, SLATE, SANDSTONE, ETC. COASTAL PLAIN SEDIMENTARY ROCK (CP) SHELL BEDS, ETC. WEATHERING	COLLUYIUM - ROCK FRAGMENTS MIXED WITH SOIL DEPOSITED BY GRAVITY ON SLOPE OR AT BOTTOM OF SLOPE.  CORE RECOVERY (RC.) - TOTAL LENGTH OF ALL MATERIAL RECOVERED IN THE CORE BARREL DIVIDED BY TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.  DIKE - A TABULAR BODY OF IGNEOUS ROCK THAT CUTS ACROSS THE STRUCTURE OF ADJACENT
*48 38 KX 55 MX 55 MX 55 MX 55 MX 35 MX 35 MX 35 MX 35 MX 36 MN 36 MN 36 MN 56	ORGANIC MATERIAL GRANULAR SILT - CLAY  ORGANIC MATERIAL SOILS SOILS  TRACE OF ORGANIC MATTER 2 - 3% 3 - 5% TRACE 1 - 10%	FRESH ROCK FRESH, CRYSTALS BRIGHT, FEW JOINTS MAY SHOW SLIGHT STAINING. ROCK RINGS UNDER HAMMER IF CRYSTALLINE.	ROCKS OR CUTS MASSIVE ROCK.  DIP - THE ANGLE AT WHICH A STRATUM OR ANY PLANAR FEATURE IS INCLINED FROM THE HORIZONTAL.
PASSING *40  LL	LITTLE ORGANIC MATTER 3 - 5% 5 - 12% LITTLE 10 - 20% MODERATELY ORGANIC 5 - 10% 12 - 20% SOME 20 - 35% HIGHLY ORGANIC > 10% > 20% HIGHLY 35% AND ABOVE	VERY SLIGHT (V SLI.)  ROCK GENERALLY FRESH, JOINTS STAINED, SOME JOINTS MAY SHOW THIN CLAY COATINGS IF OPEN, (V SLI.)  CRYSTALS ON A BROKEN SPECIMEN FACE SHINE BRIGHTLY. ROCK RINGS UNDER HAMMER BLOWS IF OF A CRYSTALLINE NATURE.	DIP DIRECTION (DIP AZIMUTH) - THE DIRECTION OR BEARING OF THE HORIZONTAL TRACE OF THE LINE OF DIP, MEASURED CLOCKWISE FROM NORTH.
GROUP INDEX 0 0 0 0 4 MX 0 MX 12 MX 16 HX NO MX AHOUNTS OF SOILS  USUAL TYPES STONE FRAGS. FINE SILTY OR CLAYEY SILTY CLAYEY HATTER  OF MAJOR GRAYEL AND SAMD SAMD SAMD SAMD SAMD SAMD SAMD SAM	GROUND WATER  WATER LEVEL IN BORE HOLE IMMEDIATELY AFTER DRILLING  STATIC WATER LEVEL AFTER 24 HOURS	SLIGHT ROCK GENERALLY FRESH, JOINTS STAINED AND DISCOLORATION EXTENDS INTO ROCK UP TO 1 INCH, OPEN JOINTS MAY CONTAIN CLAY, IN GRANITOID ROCKS SOME OCCASIONAL FELDSPAR CRYSTALS ARE DULL AND DISCOLORED, CRYSTALLINE ROCKS RING UNDER HAMMER BLOWS.	FAULT - A FRACTURE OR FRACTURE ZONE ALONG WHICH THERE HAS BEEN DISPLACEMENT OF THE SIDES RELATIVE TO ONE ANOTHER PARALLEL TO THE FRACTURE.  FISSILE - A PROPERTY OF SPLITTING ALONG CLOSELY SPACED PARALLEL PLANES.  FLOAT - ROCK FRAGMENTS ON SUBFACE NEAR THEIR ORIGINAL POSITION AND DISLODGED FROM
GEN. RATING AS SUBCRADE EXCELLENT TO GOOD FAIR TO POOR POOR POOR UNSUITABLE		MODERATE  (HOD.)  GRANITIDID ROCKS, MOST FELDSPARS ARE DULL AND DISCOLORED, SOME SHOW CLAY. ROCK HAS  DULL SOUND UNDER HAMHER BLOWS AND SHOWS SIGNIFICANT LOSS OF STRENGTH AS COMPARED  WITH FRESH ROCK.	PARENT MATERIAL.  FLOOD PLAIN (FP) - LAND BORDERING A STREAM, BUILT OF SEDIMENTS DEPOSITED BY THE STREAM.
PI OF A-7-5 SUBGROUP IS ≤ LL - 38 PI OF A-7-6 SUBGROUP IS > LL - 38  CONSISTENCY OR DENSENESS  PRIMARY SOIL TYPE  COMPACTIVESS OR RANGE OF STANDARD RANGE OF UNCONFINED PRIMARY SOIL TYPE  COMPACTIVESS OR PRIMARY SOIL TYPE	MISCELLANEOUS SYMBOLS  ROADWAY EMBANKMENT (RE) 25/025 DIP & DIP DIRECTION	MODERATELY SEVERE AND DISCOLORED OR STAINED. IN GRANITOID ROCKS, ALL FELDSPARS DULL SEVERE (MOD. SEV.) AND CAN BE EXCAMPLED WITH A GEOLOGIST'S PICK. ROCK GIVES 'CLUNK' SOUND WHEN STRUCK.  IF TESTED, WOULD YIELD SPI REFUSAL	FORMATION (FM.) - A MAPPABLE GEOLOGIC UNIT THAT CAN BE RECOGNIZED AND TRACED IN THE FIELD.  JOINT - FRACTURE IN ROCK ALONG WHICH NO APPRECIABLE MOVEMENT HAS OCCURRED.  LEDGE - A SHELF-LIKE RIDGE OR PROJECTION OF ROCK WHOSE THICKNESS IS SHALL COMPARED TO
CUNSISTENCY (N-VALUE) (TONS/FT <sup>2</sup> )  GENERALLY (SPY LOOSE 4 TO 10 GRANULAR MOTERIAL MEDIUM DENSE 10 TO 30 N/A	with soil description of rock structures  soil symbol of rock	SEVERE ALL ROCK EXCEPT OUARTZ DISCOLORED OR STAINED, ROCK FABRIC CLEAR AND EVIDENT BUT REGUCED IN STRENGTH TO STRONG SOIL. IN GRANITOID ROCKS ALL FELDSPARS ARE KAOLINIZED TO SOME EXTENT, SOME FRAGMENTS OF STRONG ROCK USUALLY REMAIN.  15 TESTED, WOULD YIELD SPT N VALUES 2 100 8PF	TTS LATERAL EXTENT.  LENS - A BODY OF SOIL OR ROCK THAT THINS OUT IN ONE OR MORE DIRECTIONS.  MOTILED (MOT.) - IRREGULARLY MARKED WITH SPOTS OF DIFFERENT COLORS, MOTILING IN SOILS USUALLY INDICATES POOR AFRATION AND LACK OF COOD DRAINAGE.
DENSE   30 TO 50	INFERRED SOIL BOUNDARY	VERY ALL ROCK EXCEPT OUARTZ DISCOLORED OR STAINED, ROCK FABRIC ELEMENTS ARE DISCERNIBLE SEVERE BUT MASS IS EFFECTIVELY REDUCED TO SOIL STATUS, WITH ONLY FRAGMENTS OF STRONG ROCK (V SEV.) REMAINING, SAPPOLITE IS AN EXAMPLE OF ROCK WEATHERED TO A DEGREE THAT ONLY MINOR VESTIGES OF ORIGINAL ROCK FABRIC REMAIN. IF TESTED, WOULD YIELD SPT N VALUES < 100 BPF	PERCHED WATER - WATER MAINTAINED ABOVE THE NORMAL GROUND WATER LEVEL BY THE PRESENCE OF AN INTERVENING IMPERVIOUS STRATUM.  RESIDUAL (RES.) SOIL - SOIL FORMED IN PLACE BY THE WEATHERING OF ROCK.
SILT-CLAY         MEDIUM STIFF         4 TO 8         0.5 TO 1.0           MATERIAL         STIFF         8 TO 15         1 TO 2           (COHESIVE)         VERY STIFF         15 TO 30         2 TO 4           HARD         > 30         > 4	INFERRED ROCK LINE MONITORING WELL TEST BORING WITH CORE  THE ALLUVIAL SOIL BOUNDARY A PIEZOMETER INSTALLATION SPT N-VALUE	COMPLETE  ROCK REDUCED TO SOIL, ROCK FABRIC NOT DISCERNIBLE, OR DISCERNIBLE ONLY IN SMALL AND SCATTERED CONCENTRATIONS, QUARTZ MAY BE PRESENT AS DIKES OR STRINGERS, SAPROLITE IS ALSO AN EXAMPLE.	ROCK QUALITY DESIGNATION (RDD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL LENGTH OF ROCK SEGMENTS EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.
TEXTURE OR GRAIN SIZE	RECOMMENDATION SYMBOLS	ROCK HARDNESS  VERY HARD CAINOT BE SCRATCHED BY KNIFE OR SHARP PICK, BREAKING OF HAND SPECIMENS REQUIRES	SAPROLITE (SAP.) - RESIDUAL SOIL THAT RETAINS THE RELIC STRUCTURE OR FABRIC OF THE PARENT ROCK.
U.S. STO. SIEVE SIZE 4 10 40 60 200 270  OPENING (MM) 4.76 2.00 0.42 0.25 0.075 0.053	UNDERCUT UNSUITABLE WASTE  UNCLASSIFIED EXCAVATION - UNSUITABLE WASTE  UNCLASSIFIED EXCAVATION - ACCEPTABLE, BUT NOT TO BE USED IN THE TOP 3 FEET OF EMBANKMENT OR BACKFILL  UNDERCUT  UNDERCUT  UNDERCUT  UNDERCUT  UNDERCUT  ON THE TOP 3 FEET OF EMBANKMENT OR BACKFILL	SEVERAL HARD BLOWS OF THE GEOLOGIST'S PICK.  HARD CAN BE SCRATCHED BY KNIFE OR PICK ONLY WITH DIFFICULTY, HARD HAMMER BLOWS REQUIRED TO DETACH HAND SPECIMEN.	SILL - AN INTRUSIVE BODY OF IGNEOUS ROCK OF APPROXIMATELY UNIFORM THICKNESS AND RELATIVELY THIN COMPARED WITH ITS LATERAL EXTENT, THAT HAS BEEN EMPLACED PARALLEL TO THE BEDDING OR SCHISTOSITY OF THE INTRUDED ROCKS.
BOULDER (COB.) (GR.) (GR.) (CSE, SD.) (F SD.) (SL.) (CL.)  GRAIN MM 305 75 2.0 0.25 0.05 0.005	ABBREVIATIONS  AR - AUGER REFUSAL MED MEDIUM VST - VANE SHEAR TEST	MODERATELY HARD  CAN BE SCRATCHED BY KNIFE OR PICK, GOUGES OR GROOVES TO 0.25 INCHES DEEP CAN BE EXCAVATED BY HARD BLOW OF A GEOLOGIST'S PICK, HAND SPECIMENS CAN BE DETACHED BY MODERATE BLOWS.	SLICKENSIDE - POLISHED AND STRIATED SURFACE THAT RESULTS FROM FRICTION ALONG A FAULT OR SLIP PLANE.  STANDARD PENETRATION TEST (PENETRATION RESISTANCE) (SPT) - NUMBER OF BLOWS (N OR BPF) OF A 140 LB, HAMMER FALLING 30 INCHES REQUIRED TO PRODUCE A PENETRATION OF 1 FOOT INTO SOIL
SIZE IN. 12 9 SOIL MOISTURE - CORRELATION OF TERMS	BT - BORING TERMINATED MICA MICACEOUS WEA WEATHERED  CL CLAY MOD MODERATELY 7 - UNIT WEIGHT  CPT - CONE PENETRATION TEST NP - NON PLASTIC 7 - DRY UNIT WEIGHT	MEDIUM  CAN BE GROOVED OR GOUGED 0.05 INCHES DEEP BY FIRM PRESSURE OF KNIFE OR PICK POINT.  CAN BE EXCAVATED IN SMALL CHIPS TO PEICES 1 INCH MAXIMUM SIZE BY HARD BLOWS OF THE POINT OF A GEOLOGIST'S PICK.	A 140 LB, HAMMER FALLING 30 INCHES REQUIRED TO PRODUCE A PENETRATION OF 1 FOOT INTO SOIL WITH A 2 INCH OUTSIDE DIAMETER SPLIT SPOON SAMPLER, SPT REFUSAL IS PENETRATION EQUAL TO OR LESS THAN 0.1 FOOT PER 60 BLOWS, STRATA CORE RECOVERY (SREC.) - TOTAL LENGTH OF STRATA MATERIAL RECOVERED DIVIDED BY
SOIL MOISTURE SCALE (ATTERBERG LIMITS)  FIELD MOISTURE DESCRIPTION  - SATURATED - USUALLY LIQUID; VERY WET, USUALLY	CSE COARSE   ORG ORGANIC	SOFT CAN BE GROVED OR GOUGED READILY BY KNIFE OR PICK, CAN BE EXCAVATED IN FRAGMENTS FROM CHIPS TO SEVERAL INCHES IN SIZE BY MODERATE BLOWS OF A PICK POINT, SMALL, THIN PIECES CAN BE BROKEN BY FINGER PRESSURE.	TOTAL LENGTH OF STRATUM AND EXPRESSED AS A PERCENTAGE.  STRATA ROCK QUALITY DESIGNATION (SROD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL LENGTH OF ROCK SEGMENTS WITHIN A STRATUM EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY
(SAT.) FROM BELOW THE GROUND WATER TABLE  PLASTIC SEMICOLID- PEQUIPES ORVING TO	F - FINE SL SILT, SILTY ST - SHELBY TUBE FOSS FOSSILIFEROUS SLI SLIGHTLY RS - ROCK FRAC FRACTURED, FRACTURES TCR - TRICONE REFUSAL RT - RECOMPACTED TRIAXIAL	VERY CAN BE CARVED WITH KNIFE. CAN BE EXCAVATED READILY WITH POINT OF PICK. PIECES I INCH OR MORE IN THICKNESS CAN BE BROKEN BY FINGER PRESSURE. CAN BE SCRATCHED READILY BY FINGERWAIL.  FRACTURE SPACING BEDDING	THE TOTAL LENGTH OF STRATA AND EXPRESSED AS A PERCENTAGE.  TOPSDIL (15.) - SURFACE SOILS USUALLY CONTAINING ORGANIC MATTER.
RANGE (PI) PL PLASTIC LIMIT - WET - (W) SENISULIS REGULARS GATHER TO ATTAIN OPTIMUM MOISTURE	FRAGS FRAGMENTS # - MOISTURE CONTENT CBR - CALIFORNIA BEARING HI HIGHLY V - VERY FOLUMENT LICED ON SUBJECT PROJECT	FRACTURE SPACING  IERM SPACING VERY WIDE  WORE THAN 10 FEET  SEDDING  IERM IHICKNESS 4 FEET	BENCH MARK: 72-0014-2, N: 912736.0200, E: 1989150.7650  ELEVATION: 559.84 FEET
OM OPTIMUM MOISTURE - MOIST - (M) SOLID; AT OR NEAR OPTIMUM MOISTURE SL SHRINKAGE LIMIT	DRILL UNITS:  DRILL UNITS:  CME-45C  DRILL UNITS:  CLAY BITS  DRILL UNITS:  ADVANCING TOOLS:  CME-45C  DRILL UNITS:  ADVANCING TOOLS:  CME-45C  DRILL UNITS:  ADVANCING TOOLS:  CME-45C  DRILL UNITS:  CME-45C  DRILL UNITS:  ADVANCING TOOLS:  CME-45C  DRILL UNITS:  CME-45C  DRILL UNITS:  CME-45C  DRILL UNITS:  ADVANCING TOOLS:  CME-45C  DRILL UNITS:  CME	WIDE	NOTES:
- DRY - (D) REQUIRES ADDITIONAL WATER TO ATTAIN OPTIMUM MOISTURE  PLASTICITY	CME-55  G' CONTINUOUS FLIGHT AUGER  CORE SIZE:  X 8' HOLLOW AUGERS  G-BH	THINLY LAMINATED < 0.008 FEET  INDURATION	TOP RAIL 1(EBISIDE) = 563.1 TOP RAIL 2 (EB2 SIDE) = 563.2
PLASTICITY INDEX (PI)   DRY STRENGTH	X CME-550	FOR SEDIMENTARY ROCKS, INDURATION IS THE HARDENING OF MATERIAL BY CEMENTING, HEAT, PRESSURE, ETC.  RUBBING WITH FINGER FREES NUMEROUS GRAINS:  GENTLE BLOW BY HAMMER DISINTEGRATES SAMPLE.	
MODERATELY PLASTIC 16-25 MEDIUM HIGHLY PLASTIC 26 OR MORE HIGH  COLOR	YANG SALAK TEST   X CASING   X W/ ADVANCER   POST HOLE DIGGER   POST HOLE DIGGER   HAND AUGER   HAND AUGER   SALIKNING ROD	MODERATELY INDURATED  GRAINS CAN BE SEPARATED FROM SAMPLE WITH STEEL PROBE; BREAKS EASILY WHEN HIT WITH HAMMER.  GRAINS ARE DIFFICULT TO SEPARATE WITH STEEL PROBE;	
DESCRIPTIONS MAY INCLUDE COLOR OR COLOR COMBINATIONS (TAN, RED, YELLOW-BROWN, BLUE-GRAY), MODIFIERS SUCH AS LIGHT, DARK, STREAKED, ETC. ARE USED TO DESCRIBE APPEARANCE.	TRICONE 'TUNGCARB. SOUNDING ROD  X CORE BIT VANE SHEAR TEST	INDURATED DIFFICULT TO BREAK WITH HAMMER.  EXTREMELY INDURATED SAMPLE BREAKS ACROSS GRAINS.	DATE: 8-15-14







## NCDOT GEOTECHNICAL ENGINEERING UNIT BORELOG REPORT


TIP SF-720014 COUNTY PERSON GEOLOGIST Mohs, N. D. WBS 41665.3E SITE DESCRIPTION BRIDGE NO. 14 ON NC 157 (GUESS RD.) OVER BYRD'S CREEK **GROUND WTR (ft)** N/A ALIGNMENT -L-0 HR. OFFSET 7 ft LT BORING NO. EB1-A STATION 16+54 COLLAR ELEV. 561.2 ft TOTAL DEPTH 21.4 ft **NORTHING** 912,740 **EASTING** 1,989,163 24 HR. FIAD HAMMER TYPE Automatic DRILL METHOD NW Casing W/SPT & Core DRILL RIG/HAMMER EFF./DATE RFO0067 CME-550X 86% 02/09/2015 **START DATE** 03/10/15 COMP. DATE 03/10/15 SURFACE WATER DEPTH N/A DRILLER Pinter, D. G. ELEV DRIVE BLOW COUNT SAMP. **BLOWS PER FOOT** DEPTH SOIL AND ROCK DESCRIPTION NO. MOI G ELEV. (ft) ELEV (ft) (ft) 0.5ft 0.5ft 0.5ft 50 75 100 DEPTH (ft) (ft) 565 **GROUND SURFACE** ASPHALT & ABC 560.0 560 ROADWAY EMBANKMENT 558.2 3.0 ORANGE, SANDY CLAY 4 M 556.8 556.6 RESIDUAL M ORANGE, GRAY, AND GREEN, SAPROLITIC, SANDY SILT 555 551.6 12 10 M 550 548.8 548.1 548.0 548.0 WEATHERED ROCK (META-VOLCANIC, SCHIST) 548.1 13.1 13.2 60/0.1 60/0.1 CRYSTALLINE ROCK 545 (META-VOLCANIC, SCHIST) GREEN, FRESH, VERY HARD, WIDE FRACTURE SPACING, FOLIATION PLANES AT 60°, META-VOLCANIC, SCHIST 540 REC=99% RQD=99% RMR=91 Boring Terminated at Elevation 539.8 ft IN CRYSTALLINE ROCK (META-VOLCANIC, SCHIST) \* ALL FRACTURES DUE TO DRILLING ACTIVITY. CONTINUOUS ROCK FROM 13.3' TO 21.4'.

/(()	CORE BORING REPORT	
	TTM CODE BODING DEDORT	
	CORL BORING REPORT	

WBS 41665.3E	TIP SF-720014 COUNT	Y PERSON GEOLOGIST Mohs, N. D.	Carlo Play
SITE DESCRIPTION BRIDGE NO.	14 ON NC 157 (GUESS RD.) O	/ER BYRD'S CREEK	GROUND WTR (ft)
BORING NO. EB1-A	STATION 16+54	OFFSET 7 ft LT ALIGNMENT -L-	0 HR. N/A
COLLAR ELEV. 561.2 ft	TOTAL DEPTH 21.4 ft	NORTHING 912,740 EASTING 1,989,163	24 HR. FIAD
ORILL RIG/HAMMER EFF./DATE RF000	067 CME-550X 86% 02/09/2015	DRILL METHOD NW Casing W/SPT & Core HAM	MER TYPE Automatic
DRILLER Pinter, D. G.	START DATE 03/10/15	COMP. DATE 03/10/15 SURFACE WATER DEPTH 1	N/A
CORE SIZE NWC3	TOTAL RUN 8.2 ft		
LEV RUN ELEV (ft) DEPTH RUN RATE (Min/ft)	REC. RQD (ft) (ft) % % SAMP. REC. RQD (ft) (ft) % % %	L O DESCRIPTION AND REMARKS G ELEV. (ft)	DEPTH (f
545 544.8 16.4 6:12/1.0 2:30/1.0 5.0 :27/0.2 /	(3.1) (3.1) (8.1) 97% 97% 99% 99% (5.0) 100%	Begin Coring @ 13.2 ft  548.0 GREEN, FRESH, VERY HARD, WIDE FRACTURE SPACE PLANES AT 60°, META-VOLCANIC, SCHIS REC=99% RQD=99% RMR=91	
540 539.8 21.4 2:15/1.0 1:54/1.0		539.8 Boring Terminated at Elevation 539.8 ft IN CRYSTAL (META-VOLCANIC, SCHIST)	LINE ROCK
		FROM 13.3' TO 21.4'.	

$\sim$ 1			_
×-	-	_	
SH		_	-

	41665				-	P SF-7			COUNT	20 K 1 7 1 2 2		_				GEOLOGIST Swartley, J. R.	T	
				DGE N	-	ON NC			S RD.) O	_		_	-	(		T	GROUND WT	-
	ING NO				_	TATION					SET	_				ALIGNMENT -L-	0 HR.	D
COLL	LAR EL	<b>EV</b> . 56	60.2 ft		T	OTAL DE	PTH	1 10.7 f	t	NOF	RTHING					EASTING 1,989,187		FIA
DRILL	RIG/HA	MMER E	FF./DA	TE RE	00067	CME-5502	X 86	% 02/09/2	015			D	RILL M	IETHO	D H	S. Augers HAMN	MER TYPE Autom	atio
DRIL	LER P	inter, D	). G.		S	TART DA	TE	03/06/1	5	CO	MP. DA	TE	03/0	06/15		SURFACE WATER DEPTH N	/A	
ELEV (ft)	DRIVE ELEV (ft)	DEPTH (ft)	BLC 0.5ft	0.5ft	JNT 0.5ft	0	25		PER FOO <sup>-</sup> 50	75 	100	0,	NO.	моі	L O G	SOIL AND ROCK DES	CRIPTION	
565	_	-								-						- - - - - 560.2 GROUND SURF ROADWAY EMBAN	KMENT	
555	556.8	3.4	10	6	2	.1								М		ORANGE, SANDY  555.8 RESIDUAL		
550	551.8	8.4	1	2	2	1								М		TAN AND LIGHT GRAY,  To 550.2		1
330	549.6	10.6	60/0.1								60/0.1				3900	- S49.6 WEATHERED R - 549.5 (META-VOLCANIC, - CRYSTALLINE F - (META-VOLCANIC, - Boring Terminated WITH - PENETRATION TEST F - Elevation 549.5 ft IN CRYS'	SCHIST) SCHIST) STANDARD REFUSAL at	1
	-	† - - - - - - - - -																
	-																	
	-																	
	-	<u></u>																
	9																	
		<del> </del> 		1												-		
		‡ ‡			2.											-		
		‡ ‡														- - - -		
		Ī														_		



## **CORE PHOTOGRAPH**

EB1-A

BOX 1: 13.2 - 21.4 FEET





## **SITE PHOTOGRAPH**

Bridge No. 14 on NC 157 (GUESS RD.) OVER BYRD'S CREEK

